

INSTRUCTION MANUAL

R-134a Recharge with A/C Leak Stop + UV Dye

LF134 & LF134H



English



A Division of Spectronics Corporation

www.tracerproducts.com 265 Spagnoli Road, #100, Melville, NY 11747 USA 800-641-1133 • 516-333-1254 Permanently seals pinhole leaks in accumulators/receivers evaporators/condensers, o-rings, and hoses while recharging the system

1. Setup

- Put on safety glasses and gloves.
- Shake can vigorously for 30 seconds.
- Start engine and set A/C to MAX COOL.
- Remove the safety cap from the can.

2. Connect

- Attach the included recharge hose/adapter, or use a compatible self-sealing hose/adapter.
- Hold can upright and turn valve slowly to purge air from hose with refrigerant. When you hear an audible release of air, close the valve.
- After purging, connect to low-side service port.

3. Charge System


- Turn can upside down. Shake gently while charging.
- Charge until empty (about 5-15 minutes), pausing to check A/C vents for cool air.
 - ▲ DO NOT OVERCHARGE: stop once the can is empty, even if before 15 minutes.
- Once empty, close the valve and wait 1 minute before disconnecting.

4. Find & Seal Leaks

- Run A/C for 15 minutes to circulate dye.
- Use a Tracerline or LeakFinder UV light to inspect system components.
- Dye glows yellow-green (always wear safety glasses).
- Wipe area and recheck with UV light to confirm seal.
- If leaks remain, system may require professional service.









Leaking System



Leaks Repaired from the Inside



HEALTH & FIRST AID

- IF IN EYES: rinse cautiously with water for several minutes and seek medical attention.
- IF ON SKIN: Exposure to skin may cause frostbite. Thaw frosted parts with lukewarm water (not hot). Do not rub affected area. Get immediate medical attention.
- IF INHALED: if high concentrations are inhaled, seek fresh air immediately. If having
 difficulty breathing provide oxygen and contact a physician immediately. If person is not
 breathing perform artificial respiration and call 911.

HANDLING & USE

- Contains refrigerant gas under pressure.
- May explode if heated.
- May cause cryogenic burns or injury.
- For servicing existing equipment only.
- Do not pierce or burn even after use.
- No smoking.
- Wear protective gloves and eye-wear when handling.

STORAGE & PROTECTION

- Protect from sunlight, store in a well-ventilated area (never in passenger cabin of vehicle).
- Do not expose to temperatures exceeding 50c/122f.
- Keep away from heat/sparks/open flames/hot surfaces.
- Keep out of reach of children.

SAFTY RISKS

- Avoid breathing vapor or mist. Avoid contact with skin and eyes.
- Intentional misuse by deliberately concentrating and inhaling contents may be harmful or fatal.
- Death can occur without warning.



A Division of Spectronics Corporation

www.tracerproducts.com

265 Spagnoli Road, #100, Melville, NY 11747 USA 800-641-1133 • 516-333-1254